



North Channel Project Update

December 19, 2022

North Connection Existing Channel Impacts



North End of Channel Project



Concrete Erosion
Protection to be formed
and poured.



East Wall of North Channel




Concrete Erosion
Protection Forms
Being Installed



East Wall of North Channel


Concrete Erosion
Protection Forms
Being Installed




West side of North Channel at dual inflow channels

**South end of
Headwall protection
for inflow channels**

**Forms for terminus of
dual concrete channels
to empty into Pond 1**



West side of North Channel at dual inflow channels



West side of North Channel at dual inflow channels









East side of North Channel Project







Avenue 40 Subgrade Channel Construction



Avenue 40 Subgrade Channel Construction



Avenue 40 Subgrade Channel Construction



Avenue 40 Subgrade Channel Construction

























